

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF-079185

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Scott Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Otero Chacra *Est.*11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 21-26N-6W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Pubco Petroleum Corporation

3. ADDRESS OF OPERATOR

P. O. Box 869, Albuquerque, New Mexico 87103

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

790' FSL & 790' FWL of Section 21-26N-6W

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6682' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)

Production Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Ran 143 joints 10 rd 3-1/2" O.D. 9.2# J-55 NEU CF&I L.S. casing (4030'). Set
at 4039.5'. Cemented with 400 sacks litepoz with 1/2# Flocele per sack plus
100 sacks Class "C" Neat. Circulated 30 sacks. P.D. @ 7:30 A.M. 9/19/72.
Pressure casing to 2500 psi. Held okay.

RECEIVED

OCT 2 1972

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.OCT 3 1972
U.S. GEOLOGICAL SURVEY
DURANGO, COLO.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. Sanders

TITLE

Area Production Manager

DATE

9/26/72

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

*See Instructions on Reverse Side