

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. MEI 03553
2. NAME OF OPERATOR Caulkins Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 780, Farmington, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' from South and 1650' from East Sec. 22 26N 6W		8. FARM OR LEASE NAME Breech D
14. PERMIT NO.		9. WELL NO. 387
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6727 DF		10. FIELD AND POOL, OR WILDCAT South Blanco-Otero Chacra
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22 26N 6West
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4022'. Ran 4 1/2" Casing as follows:

0	40.00	2 joints	5 1/2" 15.5# J-55 Smls. ST&C
40.00	3868.23	125	4 1/2" 12.6# J-55 Smls. ST&C
3068.23	4022.00	4	4 1/2" 10.5# J-55 smls. ST&C

Cemented thru shoe with 215 sacks Lodense cement followed by 195 sacks neat.
Plug down 2:45 AM 9-14-74.

Temperature survey run Sept. 14 shows top of cement at 2000'



18. I hereby certify that the foregoing is true and correct

SIGNED

Charles Deque

TITLE

Superintendent

DATE

Sept. 22, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side