

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-21424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079304

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Caulkins Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 780, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790 from the South and 820 from the West

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6623 Gr.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sanchez

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

South Blanco-Otero-Chacra

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25 26N 6W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4050 8-20-75

Ran 4 1/2" 10.5# H-40 casing to 4050' and cemented with 442 sacks
3% Lodense followed by 180 sacks neat.

Plug down 1:30 P.M. 8-21-75.

Temperature survey run 8-23-75 showed top of cement @ 780'.



SEP 8 1975

U.S. GEOLOGICAL SURVEY
DEPT. OF THE INTERIOR

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE

8-28-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side