Form 9-331 (May 1993)

UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			NM 03733
			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
l.		7. UNIT AGREEMENT NAME	
OIL GAS WELL OTHER			
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Caulkins Oil Company 3. ADDRESS OF OPERATOR			Breech
			9. WELL NO.
Post Office Box 780, Farmington, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1450 from North and 1850 from west			10. FIELD AND FOOL, OR WILDCAT
			outh Blanco-Otero Chacr
			11. SEC., T., B., M., OR BLK. AND. SURVEY OR AREA
			Section 18 26N 6W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
II. IBBRIL NO.	6204 Grou	.1	io Arriba New Mexico
16. Check	Appropriate Box To Indicate N	lature of Notice, Report, or Ot	her Data
NOTICE OF IN			NT REPORT OF:
 1		WATER SHUT-OFF X	REPAIRING WELL
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	W.J.
(Other)		Completion or Recomplet	of multiple completion on Well tion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dir nent to this work.) *	OPERATIONS (Clearly state all pertinent ectionally drilled, give subsurface local	t details, and give pertinent dates, i tions and measured and true vertical	ncluding estimated date of starting any depths for all markers and zones perti-
Spud well 12:00 Noon 6-29-76.			
Drilled 12 1/4"	hole to TD 174'. R	lan 8 5/8" 24# J-55	casing to 174 then
cemented with 18	85 sacks class B ce	ment. 2% CaCl. Plu	g down 6:15 PM 6-29-76.
Comput simpulated to symfogs			그 그릇 회사를 가는 그를 가능하다.
Cement circulated to surface.			
Tested surface	casing with 600# fo	or 30 minutes. No d	ecrease in pressure.
Pressure test run 6-30-76.			
			1007C
			1 101 19 121 6
			V 5.57 3 /
18. I hereby certify that the foregoi	ing is true and correct		
SIGNED WALL	les Cleque TITLE_	Superintenden	1t 7-3-76
(This space for Federal or State	e office use)		4- 1 -2
APPROVED BY	TITLE		DATE
CONDITIONS OF APPROVAL,			