

DAILY DRILLING REPORT

Jicarilla "H" #1-A

JICARILLA "H" #1-A  
Blanco Mesa Verde Fld  
Rio Arriba Co, NM

8/4/76

(1) 266 drlg sd, 12 $\frac{1}{4}$  hole, NND,  
Cactus Drlg Co spud 12:45 PM 8/4/76.  
COST 5947.

Spud Mud.

8/5/76

(2) 681 drlg sd & sh, 7-7/8 hole, 8.8-30-15.  
1" @ 318, drill 12 $\frac{1}{4}$  hole to 318, cond hole 1/2 hr,  
POH, ran 9 jts 8-5/8 20# K55 csg set on bottom @ 318,  
BJ cmt w/ 250x Class B + 2% CaCl<sub>2</sub>, PD 11:30 AM 8/4/76,  
cmt circ, NU test csg & BOP's to 800 psi/ok.

8/17/76

(14) 6050 ND sd & sh, 7-7/8 hole, 9.1-50-8.  
1/2 @ 5950, TD @ 3 AM 8/16/76, circ 3 hrs for log.

8/18/76

(15) 6050 logging sd & sh, 7-7/8 hole, 9.1-53-8.  
1/2 @ 6050, cond mud 3 hrs, short trip 30' fill,  
circ & cond mud 4 hrs, POH, Dresser Atlas ran Ind  
Electric log 300-TD, Compensated Density 4600-TD,  
running SW Neutron.

8/19/76

(16) 6050 ND, cmt 5 $\frac{1}{2}$  csg, 9.0-55-8.  
ran SW Neutron log 300-6019, WIH w/ DP, 30' fill,  
CO & circ 4 hrs, POH, LD DP & DC's, ran 192 jts 4 $\frac{1}{2}$   
10.5# K55 csg, set on bottom @ 6050, DV tool @ 3823,  
BJ cmt 1st stage w/ 465x 1t wt + 5# gilsonite +  $\frac{1}{4}$ #  
flocele + 300x B Neat +  $\frac{1}{4}$ # Flocele, PD 8:30 AM 8/18/76,  
lost returns last 20 bbls of displ, circ for 2nd stage.

8/20/76

(17) 6050 ND, WOC 5 $\frac{1}{2}$  csg, circ thru DV Tool @ 3823/6  
hrs, cmt did not circ, 2nd stage 735x 1t wt + 5#  
gilsonite +  $\frac{1}{4}$ # flocele tailed in w/ 100x B +  $\frac{1}{4}$ # flocele,  
cmt circ, PD 12:15 PM 8/19/76, NU, rel Cactus Rig #5  
4:15 PM 8/19/76.

9/25/76

6050 TD.

MI Aztec Well Ser DD unit 9/24/76, SDFN.

9/26/76

RU Aztec unit, inst BOP, PU & ran 3-3/4 bit & 3  
3-1/2" ODDC's & 2-3/8 CS Hydril tbg to 3800, SDFN.

9/27/76

DO DV tool @ 3823, ran bit to 5985 & D/O cmt to  
6008 PBTd, circ hole to KCl wtr & test csg to 2000  
psi & weld on bell nipple leaked, spot 300 gals 15%  
NEA @ 5886, pull 20 jts tbg, SDFN.

9/28/76

6050 TD, 6008 PBTd.  
POH 2-3/8 cut off bell nipple, ins new nipple & BOP's  
Howco test 4-1/2" csg 3500 psi OK, Schl ran GR Coll  
log 5150-6100, Schl perf Lower Mesa Verde 1/JSPF as  
follows: 5476, 48, 50, 52, 54, 56, 58, 60, 62, 64,  
66, 68, 70, 72, 74, 76, 78, 80, 82, 84, 86, 88,  
5818, 20, 22, 24, 26, 28, 34, 36, 38, 40, 42, 44,  
50, 52, 54, 56, 60, 62, 64, 66, 74, 76, 78, 5880.  
82 84 86 88 90 92 94 96 98 100