5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR	DEPARTMENT OF THE INTERIOR CONTRACT NO. 100	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
GEO204.0.12 00.1.12	Jicarilla Apache	· · · · · ·
AND DEPOSIT OF AND DEPOSIT ON WELLS	7. UNIT AGREEMENT NAME	- 1
SUNDRY NOTICES AND REPORTS ON WELLS	I	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10
reservoir. Use Form 9-331-C for such proposals.)	Or Training Off Editor (Walle	14. g
1. oil gas 🔞	Jicarilla "D"	
well well other	9. WELL NO.	7 5 5
2. NAME OF OPERATOR	13-A	
SUPRON ENERGY CORPORATION	10. FIELD OR WILDCAT NAME	
	Blanco Mesaverde	12.54 2.54 2.54
3. ADDRESS OF OPERATOR		
P.O. Box 808, Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND	SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	±
below.)	Sec. 32, T-26N, R-3W,	N.M.P.M.
AT SURFACE: 1000 ft./S; 965 ft./E line	12. COUNTY OR PARISH 13. STA	TE
AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same as above	Rio Arriba Ne	w Mexico
AT TOTAL DEPTH: Same as above	14. API NO.	- 1, -
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	24. Al 1110.	뭐 없는
REPORT, OR OTHER DATA		
	15. ELEVATIONS (SHOW DF, KDB	, AND WD)
DECLIEST FOR APPROVAL TO: SUBSTQUENT REPORT OF	7379 Gr.	<u> </u>
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	- C 2	
TEST WATER SHUT-OFF		
FRACTURE TREAT	원 등 회원 기 및 기 및	ás á
SHOOT OR ACIDIZE	15 S S S S S S S S S S S S S S S S S S S	9 t =12 f
REPAIR WELL	(NOTE: Report results of multiple comp	letion or zone
PULL OR ALTER CASING	change on Form 9-330.)	2부원 :
MULTIPLE COMPLETE	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	실존원 기계
CHANGE ZONES	그	
ABANDON*	그 그 그 그 그를 통해보고 하는 것이 되었다.	ya W
(other)		ည်ချိန့် ကို
AT DESCRIPT PROPOSED ON COMPLETED OPERATIONS (C)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di	e all pertinent details, and give perti	nent dates,
measured and true vertical depths for all markers and zones pertinen	t to this work.)*	Canons and
		살물
1. Spudded 13-3/4" surface hole at 2:30 p.m.	7-19-79.	
		취공중
2. Drilled surface hole to 261 ft. R.K.B.	그 그 그 그 그 하는 중에 다 하는 중	
	불분투호함 전 황.	9 T N
2 Dan 6 joints of 0 5/01 22 204 U 40 and	කිරිලිලික ම ය සංක්රත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත්ත	
3. Ran 6 joints of 9-5/8", 32.30#, H-40 casi	ng. Landed at 251 ft. R	Λ.Β.
	그 문을 살 등 이 사이 꽃이 다른 사이 꽃이 다른 사이 꽃이 다른 사이를 받는 것이다.	레 세월
4. Cemented with 200 sacks of class "B" with	3% CaCl. Plug-down at	4:30 a.m.
7-20-79. Cement circulated to surface.	지방학원회 및 회	2 B B
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	2 A D
5. Waited on cement for 12 hours.		취금료
J. Walted on cement for 12 hours.	요취하게 되었는 중인	2 B N
	일 다 그 그 그 그 그 그 일 없는데 그 그 그 일 살이 다 그 그 없다.	
6. Pressure-tested casing to 1000 PSIG for 1	5 minutes. Held OK.	i a m
		i Ay
Subsurface Safety Valve: Manu. and Type	Set @	Ft.
		지속 유
18. I hereby certify that the foregoing is true and correct		<u> </u>
SIGNED Klnneth E. Koddy TITLE Prod. Supt.	DATE July 23. 1979	, 44 - , 42 -
Kenneth E. Roddy TITLE FIOR. Supe.	DATE	<u>e = 7</u> f = 12 m
(This space for Federal or State office	ce use)	
,	THE CHARGE	[3 4
APPROVED BY TITLE	CALMIA	1 4
CONDITIONS OF APPROVAL, IF ANY:	A Property Name of the	Fag 1

*See Instructions on Reverse Side CON. COM.

JUL 24 1979

Ju. S. GEOLOGICAL SURVEY DURANGO, COLC.