



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

Garrey Carruthers
Governor

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 18, 1989

Mr. Gary Munson
Amoco Production Co.
3400 Southside River Rd.
Farmington, NM 87401

Re: Jicarilla Apache 102 #12E, O-9-26N-4W

Dear Gary:

An enclosed copy of the regularly scheduled bradenhead test on the referenced well indicates a casing failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector

CG/gb



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-8178

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 6-30-89 Operator Amoco Production
Lease Name T. H. 102 Well No. 12^E Location U 0 Sec 9 Twp 26^N Range 4^W
Pressure (Shut-In or Flowing) Dwt Tubing 672 Intermediate ☒ Casing 700 Bradenhead 700
PRESS BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:	
	INTERMEDIATE	CASING
5 Min.	<u>700</u>	<u>695</u>
10 Min.		<u>680</u>
15 Min.		<u>670</u>
20 Min.		<u>660</u>
25 Min.	☒	<u>650</u>
30 Min.	<u>630</u>	<u>630</u>

BRADENHEAD FLOWED:		INTERMEDIATE FLOWED:
Steady Flow	☒	
Surges		☒
Down to Nothing		☒
Nothing		☒
Gas	☒	
Gas & Water		
Water		

If Bradenhead flowed water check description below:

Clear
Frothy
Milky
Oil for
Back

Remarks: Flowed - very steady
except when valve would
ice up.

RECEIVED

By Carly L. [Signature] AUG 28 1989
Oil CON. DIV.
DIST. 3
(Position)