

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)


1. oil ☐ well ☐ gas well ☐ other ☒ Drilling
2. NAME OF OPERATOR
Marathon Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 2659 Casper, WY 82602
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1,850' FNL & 1,685' FWL Unit F
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

(other) Please see below

SUBSEQUENT REPORT OF:



5. LEASE
Contract 154
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla Apache
9. WELL NO.
14E
10. FIELD OR WILDCAT NAME
Basin Dakota Blanco M
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34, T26N, R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
30-039-22591
- ELEVATIONS (SHOW DF, KDB, AND WD)
6,566' GL, 6,579' KB

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROGRESS REPORT

See Attachments

From: 9-3-82 To: 9-19-82



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED M.E. Kugh TITLE Drilling Superintendent DATE 9-22-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

NMOCC

OCT 1 1982

FARMINGTON
RV SMN

JICARILLA APACHE #14E

9-3-82 SI. PKR LEAKAGE TEST.

9-4-82 SI. PKR LEAKAGE TEST COMPLETED, SICP = 205 & SITP = 1,758.

9-5-82/

9-9-82 SI.

9-10-82 CORRECTED HIGH PRESS BASE FROM TBG TO CSG TURNED TBG DOWN CSG TO STIPULATE P.L. FORMATION AFTER LUBRICATING BAROID SOAP DOWN CSG PREVIOUS DAY. LEFT SI FOR 3 HRS THEN OPENED TO PIT. WELL UNLOADED SOAP, WTR, ECT., FOR 1 HR THEN DIED DOWN TO 20' BLOW, LIGHT MIST W/1/2" STREAM OF WTR. LEFT OPEN TO PIT.

9-11-82 LIGHT BLOW WITH MIST, NO WTR.

9-12-82/

9-13-82 NO REPORT DUE TO WEATHER.

9-14-82 SI, WELL CEASED FLOWING TO PIT.

9-15-82 SI. WIRELINE SERVICE WILL OPEN SLIDING SLEEVE IN TBG THURSDAY OR FRIDAY IF WEATHER & ROAD CONDITIONS ARE FAVORABLE.

9-16-82/

9-19-82 SI.