

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☒ well ☐ other

2. NAME OF OPERATOR
Curtis J. Little

3. ADDRESS OF OPERATOR
P. O. Box 2487
Farmington NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1820' FSL & 1830' FWL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF

☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
NOV 09 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330)
U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.

5. LEASE
SF-079139-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
WARREN

9. WELL NO.
#8

10. FIELD OR WILDCAT NAME
S. Blanco - Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 26-T25N-R6W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
N.M.

14. API NO.
30-039-23066

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6820' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-2-82 - Reached TD: 2854 G.R.
2 7/8"

SPUD 9:00 am 10-27-82. Drld. 125' 9-7/8" hole. Ran 124' 7" 23# csg & cemented w/ 65 sx 2% CaCl & 1/4# flocele (77 cf slry) Good Circulation of cement to pit. Plug down 3:00 pm 10-27. WOC 12 hrs. Pressure tested at 600 psi. Held OK. Drld shoe 3:00 am 10-28.

RAN 90 jts 6.5# J-55 csg totaling 2829' GL PBD 2819' GR. Cemented w/ 300 sx 50-50 poz, 6% gel & 6 1/2# gilsonite followed by 50 sx Class B neat (590 cf slurry). Cement did not circulate. WOC. Ran temp. log & found top of cement at 500' GL. Plug down 10:00 am 11-1-82. Pressure to 3500 psi. Held OK.

Subsurface Safety Valve: Manu. and Type n/a Set @ 2 Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Curtis J. Little TITLE Operator DATE 11-4-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE NOV 23 1982
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

NOV 23 1982

*See Instructions on Reverse Side

FARMINGTON DISTRICT

BY SM