(SUBMIT IN TRIPLICATE)

UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office

079395

Lease No.

Unit

SUNDRY NOTICES AND REPORTS ON WEI

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

				•	Votes	<u> </u>	19.21
Well No	1	is located	660	ft. from $\begin{bmatrix} 1 \\ S \end{bmatrix}$ line and	19 8 0 ft. fron	line of sec.	33
seleni		33	25#	10W	H.M.P	• •	
(¾ B	ec. and Sec.	No.)	(Twp.)	(Range)	(Meridian)		
Undesig	nated		San J	1000	N	ev Mexico	
	(Field)			(County or Subdivision)	(1	State or Territory)	

The elevation of the derrick floor above sea level is 6857 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8 3/4" hole was drilled to 5450' 5%" O.D. 14# J-55 was set at total depth and comented with 200 sacks 50/50 possix, plug down 1:30 P.M. 7/22/57. Pressure was released in 12 hours and a temperature survey run top of cement was recorded at 4130. The plug is below pay zone and will not be drilled. Pipe tested with 1000 p.s.i. with no pressure drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations from

Company Frank C. Elliott & Orn R. Hall	
Address 703	(By Sale College
Rossell, New Mexico	(By Sante Vellett
	Title Operator

•