



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **SF 078344**
Unit **Atlas**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 11, 1958

Well No. **A-1** is located **660** ft. from **S** line and **660** ft. from **W** line of sec. **35**
SW/4 **35** **25N** **10W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
E1st1 **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6744** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-9-58 Spudded

7-9-58 Set 8 5/8", 24#, J-55, SS Casing at 197',
W/150 sx Cement containing 2% Calcium Chloride,
Cement Circulated.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Petro-Atlas, Inc.**

Address **729 East Main**

Farmington, New Mexico

By **N. B. Gove**

Title **Engineer**