

(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock  
ArizonaUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYAllottee Contr. #14-20-603-1439Lease No. Ken-No-To

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
July 14, 1959  
FARMING, 1959  
MEXICOWell No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 26NE/4 NE/4 Sec. 26  
(1/4 Sec. and Sec. No.)25N  
(Twp.)11W  
(Range)10PK  
(Meridian)East Lower Gallup  
(Field)San Juan  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 6594 ft. est.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding job, cementing points, and all other important proposed work)

TD: 5128 PFTD: 5096 Perforations: 5034-5050

Perforate 5 1/2" csg 5063-75 w/24 bullets. Ran 2" tbg w/Gulberson EVL-30 pkr @ 5057 tail pipe @ 5066 - top Baker held down 5054 - safety joint @ 5047 - swab dry - all gas no oil. Squeezed both perf (5034-5050) (5063-75) w/75 aks neat. Re-squeeze w/75 aks neat. Drill out cement 4940-5052. Re-perf 5044-50 w/24 Jet shots. Attempted to sand-oil fracs w/1000 gals lse crude + 10000# 10-20 mesh sand. RD 2900# max 3500#, tr 2500# - Sanded up after 1000# sand + 148 BD. C/O sand 5029-52 2" tbg @ 5029' seating nipple @ 4997. PFTD 5052'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Magnolia Petroleum CompanyAddress Box 2406Hobbs, New MexicoBy [Signature]Title District Superintendent