Bisti (FIELD)

DRILLING REPORT FOR PERIOD ENDING

23 (section of lease) T25N R12W

San Juan. New Mexico (TOWNSHIP OR RANCHO) DEPTHS DAY REMARKS FROM 3300'S and 660'W of NE Corner, Sec. 23, T25N, R12W, Location: NMPM, San Juan County, New Mexico. GR 6408.51 Elevation: DF 6416.0° KB 6417.53 Spudded 3:00 P.M. 8-25-58. Ran and cemented (91:) 8-5/8", 24#, J-55 2010 0 National casing at 101° with 100 sacks cement treated with 2% calcium 8-25 chloride. Good returns to surface. Flanged up and waited on to cement 12 hours. Pressure tested casing and BOP with 500 psi, OK. 8-26 Drilled 29351. 4945 8-27 2010 to 8-31 Ran Electrical Survey and Microlog. Ran and cemented (4930) 4-1/2", 4945 TD 9-1 9.5# casing at 4940 with 150 sacks cement treated with 4% gel. Displaced with oil. Released rig 10:30 A.M. 9-1-58. Checked BOP daily Mud Summary 9.3 - 9.9 #1 gal 50 - 65 sec 6.1 - 8.5 cc wt vis WL 2/32" FCContractor: Brinkerhoff Drilling Company Drillers : J. Speaker C. Adams E. Babcock CONDITION AT BEGINNING OF PERIOD

CONDITION AT BEGINNING OF				
HOLE			CASING SIZE	DEPTH SET
SIZE	FROM	то		
	1			
	1		1	
DRILL PIPE SIZES				

C. Bremer SIGNED

C. Dremer signed