

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 1
SF 078061
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injector	7. UNIT AGREEMENT NAME Carson Unit 20
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 23-20
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1977' FSL & 1766' FWL Section 20	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6454.8' KB
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 20-T25N-R11W NMPM
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED

L. Plaudy

TITLE

Div. Opers. Engr.

DATE

MAY 25 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: New Mexico O&GCC

*See Instructions on Reverse Side

PLUG AND ABANDON
SHELL OIL COMPANY

BISTI FIELD

LEASE	CARSON UNIT	WELL NO.	23-20
DIVISION	WESTERN	ELEV	6454.8 KB
COUNTY	SAN JUAN	STATE	NEW MEXICO

FROM: 5/6-10/77

NEW MEXICO
BISTI FIELD

Carson Unit 23-20
(P&A)

"FR" TD 5075. PB 5030. AFE #527936 provides funds to P&A Units 13-12, 23-14, 14-15, 31-17, 22-19 & 23-20. MI&RU Bedford. MI tbg workstring. Tried to unseat 5-1/2 Guiberson pkr w/hyd hold down; unable to do so. Found FL @ 300'. Csg was on sli vac. SD for night.

MAY 06 1977

Carson Unit 23-20
(P&A)

TD 5075. PB 5030. 5/6 Unable to unseat pkr after fill'g backside which held about 7 BW. With pkr @ 4803 est inj rate into perms w/20 BW @ 3/4 B/M @ 600 psi. Pmp'd 35 sx cmt thru tbg & pkr. Displ'd cmt in tbg to 3750'. Avg press 700 psi, max 900. WOC 1 hr; tbg on sli vac. Backed tbg off. Displ'd hole w/mud. Rec'd 65 jts tbg & left 92 jts in hole. LD tbg. RU hyd jacks. 5/7 Shot off csg @ 1380'. Spt'd 65 sx cmt @ base of stub. Pulled csg to base of Ojo Alamo Sd @ 360'. Spt'd 75 sx cmt. Pulled csg to shoe of 8-5/8 csg. Spt'd 25 sx cmt. Fin'd pull'g csg out; csg in excellent cond. Prep to install marker.

MAY 09 1977

Carson Unit 23-20
(P&A)

TD 5075. PB 5030. 5/9 Installed abandonment marker.
RD Bedford Inc.
FINAL REPORT

MAY 10 1977