


(SUBMIT IN TRIPLICATE)

Indian Agency

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. 14-20-603-1-34



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 1945 ft. from N line and 1915 ft. from E line of sec. 3
11 of Sec. 23 15-N 11-W N.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
11 ft. San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6513 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate casing jobs, cementing points, and all other important proposed work)

Total depth 5120'. Plug ed back depth 5086'.

Perforated 5-1/2" casing from 5012' to 5018' and 5026' to 5040'
 with 4 jet shots per foot. Treated perforations with 500 gallons
 mud acid followed by 30,000 gallons crude and 30,000 sand.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company
 Address Box 817
Hermington, New Mexico
 By [Signature]
 Title Dist. Mgr.

