

Section 21

(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock Ariz.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Contract # 11-20-603-1436
Tract 123
Allottee _____
Lease No. Sadie Canute

1		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 30, 19 57

Sadie Canute

Well No. 1 is located 841.7 ft. from N line and 841.7 ft. from W line of sec. 21

Sec. 21
(4 Sec. and Sec. No.)

25-N
(Twp.)

11-W
(Range)

N.M.P.M.
(Meridian)

Undesignated
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6190 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After Setting 5225' of 5 1/2" Casing on bottom at 5225' with 150 ex cement. Tested 5 1/2" Casing with 800# for 30 minutes before and after drilling Plug.
Tested OK. No Break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MAGNOLIA PETROLEUM COMPANY

Address P.O. BOX 633

MIDLAND, TEXAS

By R. T. Gorman
R. T. GORMAN
Title Division Superintendent

