



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. SP 078065

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 5, 1955

Government

Well No. 41-21 is located 660 ft. from N line and 660 ft. from E line of sec. 21

NE 21

(1/4 Sec. and Sec. No.)

25N

(Twp.)

12W

(Range)

107N

(Meridian)

Histi

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

Kelly Dushing

The elevation of the land surface above sea level is 6267.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Status: TD 4853' PRTD 4846'
8 5/8" casing @ 115', 4 1/2" casing @ 4850'
Casing collapsed at 3900'.

Proposed Work:

1. Run cement retainer to 3850'.
2. Place 10 sacks cement below retainer.
3. Plug casing with 10 sacks cement cap.
4. Install marker and abandon in accordance with USGS regulations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 705 West Municipal Drive
Farmington, New Mexico

Original signed by
E. W. SHEPARD

By E. W. Shepard
Title Exploitation Engineer