

Section 21

(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock Ariz.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Contract 14-20-603-1436

Allottee Tract 123

Lease No. Sadie Canuto

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

SEP 27 1957

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 25, 1957

Sadie Canuto

Well No. 2 is located 660 ft. from N line and 1976 ft. from W line of sec. 21

Sec. 21
(14 Sec. and Sec. No.)

25-N 11-W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Lower Gallup (Bisti)
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6466 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 275' of 3-5/8" Surface Casing on bottom at 275' with 150 ex cement. Circulated. Tested 3-5/8" Surface Casing with 300# for 30 minutes before and after drilling plug. Tested OK. No break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MARCOLIA PETROLEUM COMPANY

Address P.O. BOX 633

MIDLAND, TEXAS

By

HARVE H. MAYFIELD

Title Asst. Division Superintendent

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....