

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 1
SF 078063
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. UNIT AGREEMENT NAME Carson Unit |
| 2. NAME OF OPERATOR Shell Oil Company | 8. FARM OR LEASE NAME Unit |
| 3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290 | 9. WELL NO. 34-17 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1942' FEL Section 17 | 10. FIELD AND POOL, OR WILDCAT Bisti |
| 14. PERMIT NO. | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 17-T25N-R11W |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6402.9 KB | 12. COUNTY OR PARISH San Juan |
| | 13. STATE N.M. |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

RECEIVED
MAR 19 1984
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

P. Plaudy

TITLE

Div. Oper. Engr.

DATE

SEP 27 1987

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

[Signature]

DATE

SEP 27 1987

cc: NMO&GCC

AREA MANAGER

*See Instructions on Reverse Side

NMO&GCC

PLUG & ABANDON
SHELL OIL COMPANY

FROM: 8/26 - 9/9/77

| | | | |
|----------|-------------|----------|-------------|
| LEASE | CARSON UNIT | WELL NO. | BISTI 34-17 |
| DIVISION | WESTERN | ELEV | 6402.9 KB |
| COUNTY | SAN JUAN | STATE | NEW MEXICO |

RECEIVED
MAR 19 1984
OIL CON. DIV.
DIST. 3

NEW MEXICO
BISTI FIELD
Carson Unit 34-17
(P&A)

AUG 2 1977

"FR" TD 5032. PB 5028. 8/23: AFE 570056 provides funds to plug and abandon. RU Bedford. Ran tbg. 8/24: Finished running to PBTD. Circ. Spotted 50 sx cmt across gross perfs 4886-4995'. Laid down tbg.

Unit 34-17
(P&A)

AUG 2 1977

TD 5032. PB 5028. No report.

Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

AUG 30 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

AUG 31 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

SEP 01 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

SEP 02 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

SEP 06 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

SEP 07 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. No report.

SEP 08 1977

Carson Unit 34-17
(P&A)

TD 5032. PB 5028. 8/25 RU hyd jacks. Shot csg @ 1245;
csg stuck. 8/26 Shot csg @ 1208. Pmp trk broke down.
8/27 Rig SD. 8/29 Spt'd 50 sx cmt plug across csg stub -
Pictured Cliffs & Fruitland Coal. Pulled csg to 430 & spt'd
35 sx cmt plug across Ojo Alamo. Pulled csg to 275 & spt'd
25 sx cmt across 8-5/8 sfc csg stub. Placed 10 sx cmt plug
@ sfc. Installed abandonment marker. RD Bedford.
FINAL REPORT

SEP 09 1977

RECEIVED

MAR 19 1984

OIL CON. DIV.
DIST. 3