


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078524  
Unit SE/4



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 4, 1956, 19

Schultz-Payne

Well No. 3-14-X is located 1600 ft. from N line and 660 ft. from E line of sec. 14

SE/4 Sec. 14  
(1/4 Sec. and Sec. No.)

T 25-N R 8-W  
(Twp.) (Range)

N. M. P. M.  
(Meridian)

Ballard Pictured Cliffs Ext. San Juan County  
(Field) (County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 6961 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

January 31, 1956. Spudded well. Then had to shut down due to weather.

February 3, 1956. After drilling to 98.5' RKB - set 89' of 8-5/8" OD 24 1/2 casing at 98.5' RKB with 70 sacks cement.

Circulated cement to surface. Moved off.

Will continue drilling later.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Frank A. Schultz, Jr.

Address Box 728

Farmington, New Mexico

By C. Deeson Neal  
C. Deeson Neal, Agent in Farmington  
Title \_\_\_\_\_