

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. SF 078067

Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 17, 1957

Carson Unit
Well No. 23-14 is located 1865.2 ft. from [N] line and 2072.9 ft. from [E] line of sec. 14

SW 14 (1/4 Sec. and Sec. No.) 25N (Twp.) 12W (Range) R11N (Meridian)
Bisti (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation ~~of the derrick floor above sea level~~ is 6318 ft. (Approx. Ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 12-15-57)

12-15, 16-57 Run and cemented 8-5/8" casing at 104' with 100 sacks treated cement. Good returns to surface. Flanged up and waited on cement. Tested BOP and casing with 700 psi 15 min. O. K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 South Behrend

Farmington, New Mexico

Original signed by
By B. W. SHEPARD

Title B. W. Shepard
Farmington, New Mexico