
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Santa	Fe,	N.M.
Lease No.	1 0362	53	
Unit			

	SUNDRY	NOTICES	AND RE	PORTS ON	4	3 1957
NOTICE OF INTEN	NTION TO DRILL		SUBSEQUE	NT REPORT OF WATER	SHOT-OFF	
NOTICE OF INTEN	NTION TO CHANGE PL	ANS	SUBSEQUE	NT REPORT OF SHOOTH	IG OR ACIDIZING	
NOTICE OF INTER	NTION TO TEST WATE	R SHUT-OFF	SUBSEQUE	NT REPORT OF ALTERIA	IG CASING	
NOTICE OF INTEN	NTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTER	NTION TO SHOOT OR	ACIDIZE	SUBSEQUE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTER	NTION TO PULL OR A	LTER CASING	SUPPLEME	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTER	NTION TO ABANDON 1	NELL				
	(INDICAT	E ABOVE BY CHECK M	IARK NATURE OF REPO	ORT, NOTICE, OR OTHER	DATA)	
			•	Octo	ber 2	, 19_57
SW_16	is locat	251 (Twp.)	(Range)	nd 2050 ft. fro	m {W} line or	sec
Risti		Sett	Juan		Hew Mexi	co
(Fie	eld)	(Cou	nty or Subdivision)		(State or Territory)	
State names of and		objective sands: sho	FAILS OF WC w sizes, weights, and all other important	lengths of proposed cas	ings; indicate mudd	ing jobs, cement-
10-1,2-57	cement. G	ood returns	to surface.	Flanged up of 15 min. Ok.	and waited o	acks treate on cement.
					FILLLING OUT 9 1957 IL CON. COI	
I understand th	hat this plan of work	must receive approv	al in writing by the C	icological Survey before	DIST 3	immenced.
Company	Shell Oil Co	erany				
Address	101 South Be	brend			* 20	
	101 South Be			By	Skipard	
				By <u>B</u> W. Title Exploi	Ikinand Shepard	