


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N. M.
Lease No. 97 073007
Unit Carson Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 26, 1961

Well No. 2 is located 2553 ft. from N line and 2325 ft. from E line of sec. 14
14 Sec. 14 25N 12E 100.000
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
1st San Juan N. M.
(Field) (County or Subdivision) (State or Territory)


The elevation of the drill floor above sea level is 4011 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Operation 9-17-1

9-17-1 ran and cemented 10-3/8", 9-40, 26.0 casing at 17' with 5 sacks of cement treated with 2% calcium chloride. 1000 cement returns to surface. Flanged up and waited on cement. Pressure tested casing and OK with 10 psi test.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Holl Mill Company
Address Post Office Box 1250
Alamogordo, N. M.
By W. M. Marshall
Title Av. Exploration & Incor