

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
E. W. Mudge No. 3  
SF 078064  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT -" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injector		7. UNIT AGREEMENT NAME Carson Unit	
2. NAME OF OPERATOR Shell Oil Company		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		9. WELL NO. 22-13	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FWL Section 13		10. FIELD AND POOL, OR WILDCAT Bisti	
		11. SEC., T. R., M., OR BLK. AND SURVEY OR AREA Section 13-T25N-R12W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6384.8 KB	12. COUNTY OR PARISH San Juan	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

See attachment

NOV 6 1975

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Div. Ops. Engr.

DATE 11/4/75

(This space for Federal or State Approval)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL NOV 11 1976

M. L. SEELINGER  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

NEW MEXICO FIELD ABANDONED

LEASE	CARSON UNIT	WELL NO.	22-13 WI
DIVISION	WESTERN	ELEV	6384.8 KB
COUNTY	SAN JUAN	STATE	NEW MEXICO

FROM: 3/14 - 3/25/75

NEW MEXICO  
BISTI FIELD

Unit 22-13 WI

"FR" TD 5034. AFE #518436 provides funds to pull csg and plug & abandon well. On 3/10 unseated & pulled pkr. Tbg had soft buildup so only ran 30 jts tbg in. SD overnight. On 3/11 pmp'd hot oil w/each 30 jts of tbg.

MAR 14 1975

Unit 22-13 WI

TD 5034. RU Bedford 3/19/75. Sptd 20 sx over perfs. WOC 2 hrs. Loaded hole w/mud. SD overnight. Cond mud. Pulled tbg out of hole. RU hyd jacks & stretched csg. Indicates about 1825' of recoverable csg. Shot csg off w/1 shot. Layed down 4 jts. SD overnight.

MAR 21 1975

Unit 22-13 WI

TD 5034. 3/21 Layed down total 1824' 4-1/2" 9-1/2# J-55 csg. Csg in excellent cond. Started in hole w/tbg to spt cmt plugs. Ran tbg to 690', hit 1st bridge. Drld down to 1080' & then SD for night. 3/22 Fin'd run'g tbg to 1824'. (Csg stub) Sptd 30 sx cmt plug. Sptd 45 sx cmt plug across Fruitland Coal @ 1375'. Pulled tbg to the Ojo Alamo sd @ 295' & spt 35 sx cmt plug. Pulled tbg to the shoe of the 8-5/8 csg @ 121' & sptd 25 sx cmt plug. Sptd 10 sx cmt plug @ surface. Installed abandonment marker.

FINAL REPORT

MAR 25 1975

100-1000

100-1000