



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N. Mex.
Lease No. SP 07806L
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to Complete Well	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 13, 1957

Carson Unit
Well No. 11-13 is located 660 ft. from N line and 660 ft. from E line of sec. 13
13 (1/4 Sec. and Sec. No.) 25N (Twp.) 12E (Range) 12E (Meridian)
dist. ext. (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~surface~~ well above sea level is 6310 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings, and all other important proposed work)

Status: Total depth: 5050
Casing: 8 5/8" cemented at 233
Hole size: 7 7/8" from 233 - Total Depth

Proposed work:

1. Cement 1 1/2" drill pipe as casing at 5015' with 200 sacks construction cement.
2. Clean out to 5017'
3. Displace mud with oil.
4. Perforate four 1 1/2" jet holes/ft between 5020 - 5030.
5. Run and set tubing.
6. Flow well into production and establish initial production rate.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 33 Richards Street

Salt Lake City, Utah

By B. W. Shepard
B. W. Shepard
Title Exploitation Engineer

