

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N. M.
Lease No. SP 078067
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 27, 1957

Carson Unit

Well No. 21-14 is located 698.5 ft. from N line and 2011 ft. from W line of sec. 14

NW 14
($\frac{1}{4}$ Sec. and Sec. No.)

25N
(Twp.)

12W
(Range)

N.M.P.M.
(Meridian)

Bloti
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

kelly bushing


The elevation of the ~~shank~~ above sea level is 6271.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 12-19-57)

12-19, 20-57 Ran and cemented 8-5/8", 24#, J-55 casing at 101' with 100 sacks treated cement. Flanged up and waited on cement. Test BOP and casing with 700 psi. 15 minutes, O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 South Behrend Avenue
Farmington, New Mexico

By R. S. MacAlister, Jr.
Title Division Exploitation Engineer

100

100

100

100

100

100

100