
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| Budget B | ureau No. 4 | 2-R358 | .4. |
|-------------|-------------|---------|------|
| Form App | Sansa | Fe. | N.M. |
| Land Office | | *-*-* | |
| | SF-07 | 8067 | |
| Lease No | | | |
| | Careo | 73 | |
| Unit | | | |

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF WATER SHUT-OFF.

| NOTICE (| CE OF INTENTION TO CHANGE PLANS | | | EQUENT REPORT OF SHOOTING OR ACIDIZING. | | |
|----------------------------|--|---|--|---|--|--------------------|
| NOTICE (| CE OF INTENTION TO TEST WATER SHUT-OFF | | | | | |
| NOTICE (| OF INTENTION TO RE-DRILL OR RE | NTENTION TO RE-DRILL OR REPAIR WELLSUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | | | | |
| NOTICE (| OF INTENTION TO SHOOT OR ACID | IZE | SUBSEQUENT | REPORT OF ABAN | DONMENT | |
| NOTICE (| OF INTENTION TO PULL OR ALTER | CASING | II | | Υ | |
| NOTICE (| OF INTENTION TO ABANDON WELL. | | Conver | ted to Inje | ctor | X |
| | | | | | | |
| | (INDICATE ABO | OVE BY CHECK MARK NA | TURE OF REPOR | T, NOTICE, OR OTHE | R DATA) | |
| | | | Terms | 単心 段 | | 69 |
| | | Jewaty 18 | | | , 19 | |
| | 34) 1 | 440 | XX | 1000 | .XX | • • |
| Well No. | is located | ft. from < | N line and | 1976 1 ft. fi | $\operatorname{rom} \left\{ \frac{\mathbf{E}}{\mathbf{v}} \right\} $ line of | sec |
| SE SW | 11 | 25 N | 2 8 | MAPH | (W) | |
| | | | | | | |
| deti | Sec. and Sec. No.) | (Two Juan Ra | nge) | (Meridian) | ien Mexico | |
| | (Field) | (County or St | ıbdivision) | | (State or Territory) | |
| | | - | <i>E. P.</i> 4 4 . | | (State of Territory) | |
| The elev | ation of the derrick floor | r ahove sea level | 10 | f+ | | |
| THE CICY | delon of the defrick hoo | above sea level | 10 | 16. | | |
| | | DETAILS | OF WOR | K | | |
| (State name | es of and expected depths to objec | | | | asings: indicate muddi | na isha |
| | es of and expected depths to objec | ng points, and all other | r important pro | posed work) | and a second | ng jobs, cement- |
| $H_i^{\text{reg}}(\omega)$ | version Work | | | | | |
| | Pressure tested tui | ding with 100 | o psi. fo | r 15 minuta | es. Ok. | |
| - 0 | | | - | | • | |
| · • | Cathled while runn: | | | | | |
| | ustergent) down ca | sing. After | tubing be | came clean | , pulled. Ba | iled clean. |
| | and the state of | ra | | | | |
| . . . | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 9 4 h. C. 2 | | | | |
| . 4 | ्टिक्टर की विशेषक वर | indefeiged war | ter down | annulus to | displace uni | nhibit e d |
| | Taid, Set packer | at 4744 | , and f | illed with | inhibited wa | ter. Will |
| | - Hill than inject: | ion starts. | : :::::::::::::::::::::::::::::::::::: | | | |
| | | * | | | | FFR |
| | | | | | | 427 |
| | | | | | / 14 | <i>61 11/</i> /\\ |
| I unders | stand that this plan of work must | receive approval in writ | ting by the Geol | logical Survey befo | re operations may be c | ommen ded (|
| Compan | Andread of the control of the contro | a y | | | I WHY | 22 1962 V. COM. |
| Compan | - | | | Original | Signed By | 1982 |
| Address | P. O. Box 1200 | | | - | MARSHALL DIS | N 1 |
| nuui css | | | | *** 171. | 33 | r. SOM. |
| | Familington, N.E. | • | Е | Q., 68. 2 4. to | - Iladora | ~ / |
| | | | | By a M 。 M | | |
| | | | Tr. | DIVIOLO | n Exploitatio | n engineer |