

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, New Mex.

Lease No. SP 7404

Unit Carson

	12		
I			

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 12-12 is located 000 ft. from N line and 000 ft. from W line of sec. 12
12 (1/4 Sec. and Sec. No.) 12 (Twp.) 12 (Range) (Meridian)
12 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 4341 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Indicate 1-17-53)

3-17-50 and 3-18-50 ran and cemented 6 5/8" 24w, 8-25 casing a 99' with 100 sacks treated cement. Good returns to surface. Casing up and built on cement. Tested 24w and casing with 700 psi in min. in.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 South Second

Farmington, New Mexico

Original signed by
R. S. MacALISTER, JR.

By H. S. MacAlister

Title Exploration Engineer