

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 64224
Unit Quitau

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 21, 1954

Well No. 3 is located 1292 ft. from N line and 1300 ft. from E line of sec. 11

SE/4 SE/4 Sec. 11 25N 8W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

West Kutz Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (Not available. Will furnish later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs Sand test. Estimated depth 2300'.

Surface Casing: 90' of 8-5/8" OD 23# cemented with 75 sacks.
Production " : Approximately 2200' of 5-1/2" OD 14# J-55 cemented with 100 sacks.

If commercial production is indicated, the producing section will be shot with nitroglycerin.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN


Address 315 1/2 West Main Street

Farmington, New Mexico

By Albert H. Green

Title Field Superintendent

COMPANY Benson & Montin
LEASE Quitzau Well No 3
SECTION 11 T25N, R8W. NM.PM.
LOCATION 1292' from south line
1300' from east line
San Juan County, New Mexico



This is to certify that the above
plat was prepared from field notes
of actual surveys made by me
and are true & correct to the best
of my knowledge & belief

Robert L. Maddox Jr.
Robert L. Maddox Jr.
Registered Professional
Engineer & Land Surveyor
N.Mex. Reg. 1426

Surveyed 9-19-54

