



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe, N.M.**

Lease No. **SF 078066**

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<b>X</b>
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**July 10,** 19 **57**

Well No. **Gov't 43-10** is located **1980** ft. from **N** line and **660** ft. from **E** line of sec. **10**

**25** **10** **25** **12** **NMPN**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

**Blatt** **San Juan** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6207** ft. (Approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 7-7-57)

7-7,8-57 Ran 122' of 8-5/8", 24#, J-55 casing set at 134', cemented with 85 sacks treated construction cement. Good returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi, OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company **Shell Oil Company**

Address **101 South Behrend**

**Farmington, New Mexico**

By **B. W. Shepard**

Title **B. W. Shepard  
Exploitation Engineer**