

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency			
	Triben		
Allottee			
Lease No.	14-20-603-1424		

SUNDRY NOTICES AND REPORTS ON WELLS

SONDKI NOTICES A	ND REPORTS ON WELLS	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT.	
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL.		
(INDIGATE ABOVE BY CHECK MARK N	IATURE OF REPORT, NOTICE, OR OTHER DATA)	
-	Farmington, New Mexico Hay 1	19 <u>.57</u>
Well No. 1 is located 660 ft. from	${\bf m} {\bf N} $ line and 1500 ft. from ${\bf E} $ line of sec.	4
E/4 of Section A T-25-N (4 Sec. and Sec. No.) (Twp.)	R-12-W HPH (Range) (Meridian)	
Bisti Lower Gallup Extension San Jus	na Nextee	
(Field) (County or	r Subdivision) (State or Territory)	
The elevation of the derrick floor above sea leve	el is <u>6180</u> ft.	
	S OF WORK	
(State names of and expected depths to objective sands; show sizes ing points, and all ot	s, weights, and lengths of proposed casings; indicate mudding jol her important proposed work)	s, cement-
The name of this lease has been chang	ped from Is-Wi-De-Pah to In-Wi-De-Pa	h.
This well was spudded on March 31, 19 at 321° with 250 sacks cement. After water shut off were tested with 500 pressure. Drilling operations were a	r waiting on coment for 24 hours east counds pressure for 30 minutes with a	ing and
	91 By	70
I understand that this plan of work must receive approval in w	vriting by the Geological Survey before operations may be come	poneed.
Company Pan American Petroleum Corpos	miles	
Address Box 167	· •	- ····
Farmington, New Mexico	By	
	Title Field Clerk	