

JUN 9 1956

Budget Bureau 42-R358.2
Approval expires 12-31-56.

APPROVED.....

(Orig. Set) J. W. LONG

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 080375Unit Sheets

ACTING DISTRICT ENGINEER

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 25th, 1956

Well No. 4 is located 1000 ft. from N line and 1075 ft. from E line of sec. 1
SW/4 SW/4 Sec. 1 25N 8W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Ballard San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)
The elevation of the derrick floor above sea level is 6957 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-12-56 TD 300' in 8-3/4" hole. Reamed 12-1/4" hole to 218' RKB. Set 7 joints 206' of 8-5/8" OD 24# J-55 casing at 214' RKB with 120 sacks cement.

5-13-56 Pressured up on casing to 500#. No pressure decrease in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before work may be commenced.

Company BENSON-MONTINAddress 405 1/2 West BroadwayFarmington, New Mexico

 By [Signature]
 Title Superintendent

