Budget Bureau 42-R358.2
Approval expires 12-31-62.

APPROVED MAR 2 0 1956
(Orig. Sgd.) J. W. LONG
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 04226
Unit McManus

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED MAR 1 2 1956 U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO

March 5th, 19 56

Well No. 13 is located 990 ft. from {N/S} line and 1650 ft. from {E/W} line of sec. 4

SE/4 SW/4 Sec. 4 (¼ Sec. and Sec. No.) 25N (Twp.) 8W (Range) N.M.P.M. (Meridian)

Ballard PC (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6477 ft.

RECEIVED MAR 2 2 1956 OIL CON. COM. DIST. 3

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2- 2-56 TD 2066' RKB. Set 67 joints 2062' of 5-½/2" OD 14# J-55 casing at 2061' with 100 sacks cement.

2-20-56 Pressured up on casing to 1000#. No pressure decrease in one hour.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN

Address 405½ West Broadway

Farmington, New Mexico

By [signature]

Title Field Superintendent