
Form	9-331 8
(Feb	. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe	
Lease No.	078056	
Unit	Z	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	 	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	ļ	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	I	
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		May Zi		
Well No. 3 is local	ated 1980 ft.	from $\begin{bmatrix} N \\ S \end{bmatrix}$ line a	and 660 ft. from $\left\{m{\widetilde{E}}_{m{W}}\right\}$ line o	f sec. 6
Svi/le Mei/le	25 H	12W	MIPM	
(% Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
		San Juan	Her Hexico	
(Field)	(Co	ounty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 6199 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was perforated from h885 to h891 and h898 to h910', Schl. measure. We then fractured the fermation with 21,000 gal of oil & 25,000# of sd. Tubing was run to h929.97' and the well was swabbed to start flowing. Well started flowing 5-13-56.

1 understa	ind that this plan of work must receive approval in writing by the	Geological Survey before operations may commenced.
	Sunray Mid-Continent Oil Company	20
Address	Box 128	14/1/2/1/
	Hobbs, New Mexico	By The Star Star Star Star Star Star Star Star
		Title Field Engineer
	U. S. GOVERNMENT PRINTING OFFICE	16-8437-6

•