For	3160	-5
(Nove	mber	1983)
(Form	erly	9-331)

16.

UNITED STATES SUBMIT 1 DEPARTMENT OF THE INTERIOR **erse* alde)

BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SF-078020

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	---------	-----	----------------	----	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

	Use "APPLICATION FOR PERMIT—" for	or such propossis.)	
1.	OIL GAS THER	48 m 3 + 1 m 3: 55	7. UNIT AGREEMENT NAME Huerfano Unit
2.	NAMB OF OPERATOR		8. FARM OR LEASE NAME
	El Paso Natural Gas Company		Huerfano Unit
3.	P.O. Box 4289, Farmington, NM 87499		9. WELL NO. 154
4.	LOCATION OF WELL (Report location clearly and in accordance of See also space 17 below.) At surface 790 'N, 1650 'W	with any State requirements.*	10. FIELD AND POOL, OR WILDCAT Undes. Pictured Cliff 11. EDC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 1, T-25N, R-10W N.M.P.M.
14.	PERMIT NO. 15. ELEVATIONS (Show w	hether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6786' GL		San Juan NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

				· · · · ·		
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON®		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)		
(Other)				(Note: Report results of Completion or Recompletion	multiple completion on Well on Report and Log form.)	
		ana mana di Cianta da	<u> </u>	(Note: Report results of Completion or Recompletion	multiple completion on Well in Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

The following surface rehabilitation has been completed to BLM specifications stated in the letter 3162.3-4

- 1. Permanent monument cemented in wellbore. Labeled w/operators name, well name & number, legal location and lease number.
- 2. Location cleaned of debris & trash. Oily soil or fluids properly disposed of.
- 3. Pits are filled in and pads shaped to conform to terrain.
- 4. Pads leveled.
- 5. Access roads are leveled, waterbarred, disked and blocked off with earthen berms at the junction with the main road and at the entrance to the well pad. Waterbars were spaced as BLM specified.

6. All disturbed areas were se	eded July 12,		AUG 1 9 1988
18. I vereby certify that the foregoing is true and corre	•ct	/ 402 67668 	FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO
	TITLE Regula	atory Affai rs	DATE July 20, 1988
(This space for Federal or State office use) APPROVED BY	TITLE		DATE