

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 3
SF 078064

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		9. WELL NO. 42-24
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1880' FNL & 560' FEL Section 24		10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 24-T25N-R12W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6465' KB		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attachment

NOV 6 1975

18. I hereby certify that the foregoing is true and correct

SIGNED

J. W. Dinnel

TITLE Div. Opers. Engr.

DATE 11/4/75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

NOV 11 1976

TITLE

DATE

M. L. S. 11/11/76
J. G. D. 11/11/76

*See Instructions on Reverse Side

WELL PLUGGED AND ABANDONED

SHELL OIL COMPANY

FROM: 10/8 - 10/10/75

LEASE CARSON UNIT

DIVISION WESTERN

COUNTY SAN JUAN

WELL NO.

ELEV

STATE

BISTI

42-24

6465 KB

NEW MEXICO

NEW MEXICO

BISTI FIELD

Carson Unit 42-24

"FR" TD 5010. Operation to P&A well; AFE #520716. RU csg pulling unit. PU 2-3/8 tbg & tagged btm. Well started flw'g thru csg & press'd up to 75 psi. Pulled 2 jts tbg & shut well in. High winds blowing oil across land.

OCT 08 1975

Carson Unit 42-24

TD 5010. Pulling csg. Blew well down. Circ'd hole w/mud. Mixed 15 sx gel. Spt'd 35 sx cmt plug on btm @ 4929. (Theoretical fillup to 4779) Pulled tbg. RU csg jacks; found csg freepoint @ 1150'. Could not work lower. Shot csg off @ 1131'. Pulled csg up to 1125 & broke circ. Spt' 35 sx cmt plug on top of csg stub. (Theoretical fillup to 975')

OCT 08 1975

Carson Unit 42-24

TD 5010. Well abandoned. Pulled 4-1/2" csg to 400'. Spt'd 45 sx cmt plug. (Theoretical plug from 400-250) Pulled 4-1/2" csg to 180'. Spt'd 35 sx cmt plug. (Theoretical fill 180-80') Pulled remainder of 4-1/2" csg & spt'd 10 sx cmt plug @ surface & erected permanent abandonment marker. Rec'd 37 jts (1140') 4-1/2" csg. Well P&A.
FINAL REPORT OCT 10 1975