.19....

3

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau N	Io. 42-R358.4.
Approval expires	12-31-60.

Land Office Santa Ps. N.M.

Lease No. SF. 078063

Unit Carson

	SUNDRY NO	OTICES A	AND REI	PORTS	ON WEI	LLS	
NOTICE OF INTEN	NTION TO DRILL		SUBSEQUE	NT REPORT OF	WATER SHUT-OFF		
	TION TO CHANGE PLANS.				SHOOTING OR ACID		
	NTION TO TEST WATER SH		SUBSEQUE	NT REPORT OF	ALTERING CASING.	ا مر	
	NTION TO RE-DRILL OR F		SUBSEQUE	IT REPORT OF	RE-DRILLING OR RI	PAIR	1 4 8
	NTION TO SHOOT OR ACID				ABANDONMENT	······	101 1 9
	NTION TO PULL OR AÈTER NTION TO ABANDON WELL.		1 11		151081		(E) E) (
TOTICE OF INTER	TION TO ABANDON WELL.					U.5.	0.50.50 <sup>3</sup> , 0.50.50 <sup>3</sup> ,
· · · · · ·	(INDICATE AB	OVE BY CHECK MAR	K NATURE OF REPO	ORT, NOTICE, OR	R OTHER DATA)	<b>EV</b> ELL	
<i>y</i> *	- The #4		••		July 17		., 197
ell No. 34-	a Unit 19 is located	660 ft. from	$m_{-}\begin{bmatrix} N \\ S \end{bmatrix}$ line a	nd <b>.1980</b>	ft. from $\mathbb{R}^{E}$ 1	ine of sec.	19
SE 19 (1/2 Sec. and	d Sec. No.)	25% (Twp.)	(Range)	(Meric	dian)		
Bisti		San County	on Cub districtors)		Sou April	9	
(Fie	eld)	(County	or subdivision)		(State or Te	rriwry)	
(Spudded	d expected depths to obje	ing points, and all	other important	oroposed work)	•		
12 <b>,13<del>-5</del>7</b>	sacks treated Flanged up an with 700 psi,	construction is valued on	on coment.	Good ea	ment return	s to sur	face.
						A CON	UN
I understand th	hat this plan of work mus	st receive approval i	n writing by the (	eological Surv	ey before operation	may be comm	anced.
ompany 🕵	11-011-Company	<b>y</b>					en e
ddress - 40	-South-Behren	<b>d</b>			Original	signed by	
<del></del>	raington, New	*exico	-	Ву	R. S. Mac	ALISTER, J	ir, 
			-	Title S.	. Mac Alisto ion Exploi	r, Jr. ation 2	gineer