



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe, N.M.
Lease No. SF 078063
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Subsequent Report of Well Completion</u>	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 2, 19 58

Carson Unit
Well No. 34-19 is located 660 ft. from SW line and 1980 ft. from E line of sec. 19
SE 19 25N 11W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bloti San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

Kelly Bushing
The elevation of the ~~surface~~ above sea level is 6456 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 7-20-57 Cemented 4-1/2" 9.5# casing at 4998' with 150 sacks construction cement.
- 8-2-57 Perforated four 1/2" holes/ft. 4846-54', 4885-89', 4903-13', 4927-37', 4944-53'.
- 8-7-57 Fracture treated with 30,000 gal. crude oil and 1#/gal. 20-40 mesh sand.
- 8-11-57 Bailed sand to 4990'. Ran tubing to 4824'.
- 10-13-57 Finished installing artificial lift. Pumped 24 hrs, 53 bbls. gross, all frac. oil,
- 12-21-57 Initial Production: Pumping 30 B/D gross, 30 B/D clean, 9.1% cut, 64/64" bean, 13.5 MCF/D gas, GOR 450.

Completed 12-21-57

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address 101 South Behrend
Farmington, New Mexico

Geological signed by
B. W. SHEPARD
By B. W. Shepard
Title Exploitation Engineer