

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R368.4
Approval expires 12-31-60.

Land Office Santa Fe, N.M.
Lease No. SP 076063
Unit Carson

RECEIVED

MAR 13 1958

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 32-19 is located 1960 ft. from [N] line and 1960 ft. from [E] line of sec. 19
March 11, 19 58

NE 19 (1/4 Sec. and Sec. No.) 25N (Twp.) 11W (Range) MTN (Meridian)
Bisti (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


Kelly Bushing
The elevation of the surface above sea level is 6451.9 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 3-3-58)

3-3, 4-58 Ran and cemented 8-5/8", 24' at 108' with 100 sacks treated cement.
Good returns to surface. Flanged up and waited on cement. Tested BOP
and casing with 700 PSI 15 min. OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address 101 South Main Avenue
Farmington, New Mexico

By E. W. Shepard
Title Exploitation Engineer