

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
L. M. Phillips No. 1
SF 078063
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Carson Unit	
2. NAME OF OPERATOR Shell Oil Company		8. FARM OR LEASE NAME Unit	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290		9. WELL NO. 32-19	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL Section 19		10. FIELD AND POOL, OR WILDCAT Bisti	
11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Section 19-T25N-R1W		12. COUNTY OR PARISH San Juan	
13. STATE N.M.		14. PERMIT NO.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6452 KB		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *			


See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

APPROVED

JUN 29 1978

R. T. McGRATH
DISTRICT ENGINEER



18. I hereby certify that the foregoing is true and correct

SIGNED R. Planty TITLE Div. Ops. Engr. DATE SEP 27 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC

NEW MEXICO OIL CONSERVATION COMM.
1000 RIO BRAZOS RD.
AZTEC, NEW MEXICO 87410
See Instructions on Reverse Side

PLUG & ABANDON

SHELL OIL COMPANY

FROM: 8/10-11/77

LEASE CARSON UNIT

DIVISION WESTERN

COUNTY SAN JUAN

BISTI

WELL NO. 32-19

ELEV 6452 KB

STATE NEW MEXICO

NEW MEXICOBISTI FIELDCarson Unit 32-19
(P&A)

"FR" TD 5015. AFE #529676 provides funds to plug and abandon well. 8/8 RU Bedford. Ran tbg workstring to btm. Circ'd w/mud. Spt'd 25 sx cmp plug across & above perfs. Pulled & LD tbg workstring. 8/9 RU hyd jacks. 4-1/2" csg stuck @ 500'. Shot 4-1/2 collar @ 1395 & spt'd 50 sx cmt plug. Displ'd 20 sx cmt thru shot collar. Perf'd 4 holes/ft @ 410. Spt'd 30 sx cmt plug. Displ'd 20 sx thru perf'd holes.

AUG 10 1977

Carson Unit 32-19
(P&A)

TD 5015. Placed 10 sax cement @ surface. RD Bedford.
Installed abandonment marker.
FINAL REPORT

AUG 10 1977