Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Interior Verse side)

GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE* (Other instructions on reForm approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

| N.M. 036254 |
|-------------|
|-------------|

| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTEE OF TRIBE NAME | |
|---|---|--|
| OIL GAS WELL OTHER Water Injection | 7. UNIT AGREEMENT NAME Central Bisti Unit | |
| Sunray DX Oil Company | 8. FARM OR LEASE NAME | |
| ADDRESS OF OPERATOR | 9. WELL NO. | |
| P. C. Box 1416, Roswell, New Mexico | GI-L | |
| LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) | 10. FIELD AND POOL, OR WILDCAT | |
| At surface | 50 . 4 a | |

1980' FNL & 1980' FEL

Bisti Lower Gallup 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA

Sec. 6-25N-12W

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 6178 GL San Juan

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL. FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* Confine water injection REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *
- Lubricated ed. down the and filled cag to depth of 4857.
- Ran dump boiler through the and placed 3' cat cap on top of ad. (4857-54). 4823-43 are only ones now open.
- 3. Return well to injection service.
- Ran radio active survey and found 69% of injection water going into perfs 31% going down car.

JUL 29 1965

U. S. GEOLOGICAL SURVEY FARMER TON, R. M.

OIL CON. COM DIST. 3

| 18. I hereby certify that the foregoing is true and co | Pront | |
|--|-------|--------------------|
| SIGNED B.F.Bra | | DATE July 22, 1965 |
| (This space for Federal or State office use) | | |
| APPROVED BY CONDITIONS OF APPROVAL, IF ANY: | TITLE | DATE |