## UNITED STATES SUBMIT IN TRIPLICATE\* MENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY			NOO-C-14-20-3778		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
Use "AF	PLICATION FOR PERMIT—" for such pr	oposals.)	Navajo 7. UNIT AGREEMENT NAME	<del></del>	
OIL GAS X OTI	IER		1. UNIT AGREEMENT NAME		
NAME OF OPERATOR			8. FARM OR LEASE NAME	1 2 3	
Union Oil Company of California			Navajo(I-1)		
P. O. Box 2620 - Casper. WY 82601			9. WELL NO.		
P. O. Box 2620 - Casper, WY 82601  LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WII	LDCAT	
See also space 17 below.) At surface			Basin Dakota		
1500' FSL & 1150' FEL			11. SEC., T., R., M., OR BLK.	IND	
			SURVEY OR AREA	•	
			Sec. 1, T.25N.,		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,		12. COUNTY OR PARISH 13.		
	6431' G.	L.	San Juan New	Mexico	
18. Chec	k Appropriate Box To Indicate N	ature of Notice, Report, or	Other Data		
NOTICE OF	INTENTION TO:	SUBSI	EQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	,	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	\	
REPAIR WELL	CHANGE PLANS	(Other) Supplement	ary Well History	Zeil	
(Other)	ED OPERATIONS (Clearly state all pertinent directionally drilled, give subsurface locat		its of multiple completion on Winpletion Report and Log form.)		
perfs with fluid  SITP zero. MIRU well kicked off f on 12/64" choke. 5 bbls. oil. Rel  SITP 1700#/17 hou 10 bbls. condensa  SITP 1700#/18 hou  I.P (6-19-76)	radioactive tracer surve movement up to 6188' and swab unit. Swabbed 20 b lowing. Flowed water an FTP 500# the last hour. eased rig and shut in. rs. Flowed to pit on vate and 50 bbls. gas-cut ers.  Flowed 24 hours on 28/64 Press. 80#.	down to 6172'. S. bls. load water/3 h d gas to pit/6 hour Recovered approxi rious chokes 2 hour water. Well appear	I. 13 hours.  ours. F.L. 900-120 s to clean up. Flo mately 85 bbls. was s. FTP 280#. Reco ed to dry up and c	00' and owed gas ter and	
			The way were the same of the s	Walter Control of the	
18. I hereby certify that the foreg	oing is true and correct				
SIGNED R. G	. Ładd, Jr.	trict Drilling Supt	. DATE 7-16-76	5	
(This space for Federal or Sta	ate office use)		1		
APPROVED BY			DATE	_ ز	
CONDITIONS OF APPROVAL				Ì	
			jiji 1, 9, <b>1</b> 976	<b>2</b> 61 21	
	*See Instructions	on Reverse Side	<b>u. s</b> . com oggan grjad	· · · · · · · · · · · · · · · · · · ·	
		'	and the second of the second o		