

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

Oklahoma Oil Company

3. ADDRESS OF OPERATOR

Texas 75206
4925 Greenville Ave., One Energy Square, Dallas

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

1730' FNL & 975 FWL

AT SURFACE:

AT TOP PROD. INTERVAL: same

AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐(other) ☐5. LEASE
N00-C-14-20-5369

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo 4

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Nipp Pictured Cliff

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec 4 - 25N

12W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6097 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in and rig up L & B Speed Drill. Spud at 10:30 a.m. 11-1-77. Drilled 7 7/8" hole to 46'. Ran one joint 5 1/2 casing and set at 46'. Cemented with 7 sacks class "B" cement. Circulated cement returns. Plug down at 4:00 p.m. 11-1-77. Wait on cement 12 hours. Drilled 4 3/4" hole to 110'. Total depth at 6:00 p.m. 11-3-77. Ran open hole logs IES, FDC-CNL, Caliper and GR. Ran 36 joints 2 7/8" casing and set at 1107'. Cemented with 100 sacks class "B" cement. Plug down at 2:37 p.m. 11-4-77. Wait on cement. Wait on completion unit.

Subsurface Safety Valve: Manu. and Type

none

18. I hereby certify that the foregoing is true and correct

SIGNED

William T. Jones
William T. Jones

TITLE

Agent

DATE

11-7-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

NOV 8 1977

U.S. Geological Survey
Farmington, N.M.