

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 42-R1111

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | | |
|---|--|--|-------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | | 5. LEASE DESIGNATION AND SERIAL NO. N M 5459 | |
| 2. NAME OF OPERATOR Southern Union Exploration Company | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 3. ADDRESS OF OPERATOR Suite 1800, First International Bldg, Dallas, Texas 75270 | | 7. UNIT AGREEMENT NAME | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650 FNL, 1650 FWL | | 8. FARM OR LEASE NAME Grynberg Federal | |
| 14. PERMIT NO. | | 9. WELL NO. 1 | |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6421 GR | | 10. FIELD AND POOL, OR WILDCAT Wildcat | |
| | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec18, T25N, R13W NMPM | |
| | | 12. COUNTY OR PARISH San Juan | 13. STATE New Mexico |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PEEL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Temporary Abandonment ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/25/78 - No measurable flow, closed in production string at surface with 2000# W.P. valve.

Presently evaluating for possible future development.



18. I hereby certify that the foregoing is true and correct

SIGNED

Ronald A. Santz

TITLE: Drilling & Production Engr. DATE: 1/31/79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC