5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	NOO-C-14-20-5503  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
decedient sonver	Navajo Tribe
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
escryoir. Use Form 9-331-C for such proposals.)	· I
1. oil gas well other	Navajo Tribal "AG"  9. WELL NO.
2. NAME OF OPERATOR	1 10. FIELD OR WILDCAT NAME
Amoco Production Company	-
3. ADDRESS OF OPERATOR 501 Airport Drive Farmington, NM 87401	Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 990' FNL x 1790' FWL Section 14,	NE/4 NW/4 Section 14, T25N, R14W 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same T25N, R14W	San Juan New Mexico
AT TOTAL DEPTH: Same	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-045-23658
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6112 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6112 GL
TEST WATER SHUT-OFF	
RACTURE TREAT	
SHOOT OR ACIDIZE  REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	(NOTE: Report results of multiple completion of 2016
MULTIPLE COMPLETE	- · · · · · · · · · · · · · · · · · · ·
CHANGE ZONES	and the second of the second o
ABANDON* L X	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give substituace locations and
Amoco Production Company plugged and abandon	ed the subject well on 10-7-79.as
follows:	
(1) Set 8-5/8" cement retainer at 900'.	300' 400'
(2) Spotted with 30 sx class "B" Neat cement	
(3) Spotted with 10 sx class "B" Neat cement	from 0' - 30'.
(4) Cut off bradenhead, erected PXA marker,	and cleaned up location.
(4) 000 011 510000000	
The following casing was left in the hole:	A Real Section of the
10-3/4" 249' (0-249	1) 101/2/8/197
8-5/8" 916' (0-916	OIL CON. CO
	\ =\AT 4
Subsurface Safety Valve: Manu. and Type	Set @DISt.
18. I hereby certify that the foregoing is true and correct Original Signed	Comm. 11/1/70
SIGNED E. E. SVOBODA TITLE Dist. Adm.	SUPI DATE
(This space for Federal or State office use)	
APPROVED BY DATE	
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	