5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	SF078064
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Carson Unit
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🗵 other	9. WELL NO. 203
2. NAME OF OPERATOR Hixon Development Company	10. FIELD OR WILDCAT NAME
3 ADDRESS OF OPERATOR	Pictured Cliffs
P.O. Box 2810, Farmington, New Mexico 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Section 13-T25N-R12W
below.) AT SURFACE: 1620' FSL, 1630' FEL 13-25-12	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO:  TEST WATER SHUT-OFF   FRACTURE TREAT	6405' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT	
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	
REPAIR WELL     MAR	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	W. Cususe on Louin 3-2203
CHANGE ZONES	ကြောင်းကြောင့် မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ ကြောင်းကြောင့် မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သည်။ မြောက်သ
REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  ABANDON*  MULTIPLE COMPLETE  U. S. GEOLOGICAL SU  FARMINGTONIA	
(other)	
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dis measured and true vertical depths for all markers and zones pertinent</li> </ol>	ecupitativ difficu, give substituce totations and
Rigged up 2/23/83 and swabbed well to determin	
formation water with gas too small to measure.	
and abandon well as follows: fill casing from	
35 sacks (41 cubic feet) cement. Cut off well	head and set regulation
marker.	
ANTA CARACTER STATE	그 소리 : 요즘 회원의 호텔 () 항화 :
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I Hereby certify that the foregoing is true and correct	
A conservation Engi	neer <sub>DATE</sub> 3/2/83
(This space for Federa or State offi	
TITLE	DATE A DEBOYED
CONDITIONS OF APPROVAL, IF ANY:	AS AMENDED
*Contrations on Payersa S	MAR 9 8 1983