K M PRODUCTION COMPANY

Bench #1 Section 34, T25N, R13W San Juan County, New Mexico

SLOPE TESTS

Depth	Hole Deviation
88 ft.	0°
905 ft.	1/8°
1185 ft	1/4°



		OIL CON. COM. DIST. 3
State of New Mexico)		
County of San Juan)	S	
I, KEVIN H. McCORD the above and foregoing d to the best of my informa	being first duly sworn, epth and hole deviation figure tion and belief.	depose and state that s are true and correct
	Levin	H Myord
Subscribed and sworn befo	re me this 8th day of Apr	i1, 1981
		sieft redi
	•	Notary Public
My Commission Expires	09-20-84	•