UNITED STATES SUBMIT IN TRIPLICATE (May 1933) DEPARTMENT OF THE INTERIOR verse aide) GEOLOGICAL SURVEY	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	8. IF INDIAN, ALLOTTEE OR THIBE NAME
I. OIL GAS X OTHER	7. UNIT AURECMENT NAME
2. NAME OF OPERATOR Dugan Production Corp.	8. FARM OR LEASE NAME
Box 208, Farmington, NM 87401	9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL - 1650' FEL	10. FIELD AND POOL, OR WILDCAT Undesignated PC 11. SEC., T., E., M., OR BLE. AND BURYET OR AREA Sec. 7 T25N R12W
14. PERSHIT NO. 15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6248 GR	12. COUNTY OF PARISH 13. STATE San Juan NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, a	or Other Data
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING WELL ALTERING CARING ABANDONMENT* Ults of multiple completion on Well
	ompletion Report and Log form.) ites, including estimated date of starting an
nent to this work.) *	
Plugged and Abandoned as follows:on May 23, 1979:	
1. Spotted 10 sx cement plug 1216-916'	
2. Spotted 7 sx cement plug 200' to surface.	
3. Cut csg and tbg off 5' below ground level.	
4. Cleaned location and filled pits on June 13, 1979.	JUN 2 3 1982 OIL CON. COM. DIST. 3
18. I hereby certify mak the toregoing is true and correct	· · · · · · · · · · · · · · · · · · ·

SIGNED THOMAS A DUCAN

(This space for Fide A) PURILLE Petroleum Engineer

APPROVED BY
CONDITIONS OF APPROVALIJATIONS OF DISTRICT ENGINEER *See Instructions on Reverse Side