

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other
2. NAME OF OPERATOR  
Hixon Development Company
3. ADDRESS OF OPERATOR  
P.O. Box 2810, Farmington, NM
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1850' FSL, 1650' FWL, 21-25-11  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

## FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL CR ALTER CASING

MULTIPLE COMPLETE

## CHANGE ZONES

ABANDON\*

(other)

## SUBSEQUENT REPORT OF

RECEIVED  
AUG 3 1983

AUG 3 1964  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

Report results of multiple completion or zone change on Form 9-330.)

**RECEIVED**

AUG 22 1983

OIL CMA. DIV  
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Cement top behind this well's 5-1/2" casing is at 2102' KB. Pressure tested 5-1/2" casing to 2000 psi 7/16/83 with no bleed off after 30 minutes.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert L. Fisher TITLE Petroleum Engineer DATE 7/29/83

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE \_\_\_\_\_

**ACCEPTED FOR RECORD**

AUG 19 1983

\*See Instructions on Reverse Side

**NMOCC**

FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO  
BY smm