

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NOO-C-14-20-5199
2. NAME OF OPERATOR Union Oil Company of California	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo
3. ADDRESS OF OPERATOR P. O. Box 2620 - Casper, WY 82602-2620	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL & 940' FEL (NE SE)	8. FARM OR LEASE NAME Federal
14. PERMIT NO. API No. 30-045-26437	9. WELL NO. 1-E *
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6574' GR (Ungraded)	10. FIELD AND POOL, OR WILDCAT Basin Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24, T.25N., R.11W.
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6138' T.D.
8-5/8" @ 782' w/530 sx cmt
4-1/2" @ 6135' w/1400 sx cmt

*Formerly Navajo (I24) Well No. 10
Drilled in 1985

Perfs: 5962-6000' - Covered w/casing patch
6022-6030' - Open
6048-6064' - Retainer set above at 6043'

Plugged and Abandoned Subject Well as Follows:

MIRU well service unit on 4-4-86. Blew well to pit from 320 psi to 0 psi. Pumped 20 bbls. water down tubing and 30 bbls. water down casing with well on vacuum. N.D. Xtree and N.U. BOP. P.U. and ran in with 3 jts. 2-3/8" tubing. Tagged at 5959'. Strapped out with tubing, O.K. S.I.O.N.

SICP 100 psi. T.P. slight blow. Finished TIH with 2-3/8" tubing. Set down at 5959'. Circulated hole with 82 bbls. water. Spotted 50 sacks of cement from 5959-5200' (Plug No. 1). P.O. to 5200'. Circulated hole with 82 bbls. 9.4#/gal. NaCl₂ mud. P.U. and laid down tubing to 5000'.

(Continued on Attached Sheet)

I hereby certify that the foregoing is true and correct

SIGNED R. G. Ladd, Jr.

TITLE District Drilling Supt.

DATE 4-10-86

This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
DATE

Surface location is complete.

*See Instructions on Reverse Side

NMOCC

APR 25 1986

AREA MANAGER

Union Oil Company of California
Federal Well No. 1-E
Basin Dakota Field
San Juan County, New Mexico
4-10-86
Page 2

Spotted 10 sacks cement from 5000-4850' (Plug No. 2). P.U. to 2350'.
Spotted 10 sacks of cement from 2350-2200' (Plug No. 3). P.U. to 1500'.
Spotted 10 sacks of cement from 1500-1350' (Plug No. 4). P.U. to 850'.
Spotted 10 sacks of cement from 850-700' (Plug No. 5). N.D. BOP and casing
spool. TIH with 2 jts. 2-3/8" tubing to 60'. Spotted 10 sacks of cement
from 60' to surface (Plug No. 6). C.I.P. and J.C. at 5:00 p.m., 4-5-86.
Cut off 8-5/8" casing 4' below ground level. Welded plate on 8-5/8" casing.
Installed dry hole marker. Well plugged and abandoned on 4-5-86.

Note: A sundry notice will be submitted as soon as the location is ready
for inspection.